DAIMLER REBUILD BODYWORK – INTERIOR – EXHAUST SYSTEM

	PARTS	LAB	TOTAL
INTERIOR- Leather clean / dyed (mink)		460	
Headlining Replaced		490	
Carpet all replaced in Cinamon (BAS) renew Furflex	320	298	
Door seals Lower RH &LH Upper (1)	40		£1608
EXTERIOR- Panels Rear valence Both outer cills	161		
Replace Rear bumper 3 sections & Front underiders	600		
Replace overiders rear Replace Front Plinths & Caps	219		
Replace Mirrors Badges	323		
Headlamp Bezels (2) Both F. Side .NS Repeater	210		
PAINT –WAXOIL- REBUILD Fit the above	760	4334	£6607
WHEELS: 5 (Lattice Alloys) Blast Spray &finish			£ 401
TYRES 5 Pirelli P7 225/60/R15 96W			£
PETROL Tanks & Sendors & Filler Cap Seals Replaced			£ 370
EXHAUST Y Pipe/ Front Silencer(2) Inter pipes	328	146	
Rear Boxes & Chrome Trims	200	36	£ 710
SUBFRAME REAR & Bumpstops	240	260	£ 500
BATTERY & ALTERNATOR			£ 217
FRONT CROSS MEMBER Replaced			£ 514

PAGE TOTAL **£ 10,927-00**

P